

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-08 07:57:58
Technician Name: Raymond
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2017
Make: LANDROVER
Model: Discovery Sport
VIN: SALCA2AN3HH700410
Odometer: 118427 km
Vehicle Software Version: V10.46

Inspection Result

IPMA (Image Processing Control Module A) 1 problems exist

1.C1001-78 Automatic High Beam Camera

Permanent

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.IPC (Instrument Cluster Control Module)
- 6.BCM (Body Control Module)
- 7.SASM (Steering Angle Sensor Module)
- 8.GSM (Gear Shift Module)
- 9.AWDCM (All Wheel Drive Control Module)
- 10.GWM (Gateway Module)
- 11.HCM (Headlamp Control Module)
- 12.TCU (Telematic Control Unit Module)
- 13.PAM (Parking Assist Control Module)
- 14.PSCM (Power Steering Control Module)
- 15.AHU (InControl Touch Audio Head Unit)
- 16.HVAC (Heating Ventilation And Air Conditioning Control Module)
- 17.IPMB (Image Processing Module B)
- 18.SODL (Side Object Detection Control Module-Left)
- 19.SODR (Side Object Detection Control Module-Right)

- 20.DDM (Driver's Door Module)
- 21.DRDM (Driver's (Side) Rear Door Module)
- 22.RFA (Keyless Vehicle Module)
- 23.PDM (Passenger's Door Module)
- 24.PRDM (Passenger's (Side) Rear Door Module)