

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 17381

Make	NISSAN		
Model	MICRA 1.5 TEKNA 5DR (D85)		
Vin	MDHFAUK13Z050090	99	
Engine Specifications	1.5	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2013
Km	96739
Transmission	Manual
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	•	Aircon Controls	Working Condition	•
Cluster	Working Condition	•	Electric Windows	Working Condition	•

Exterior					
Windscreen	Not Applicable	•	Mag Wheels	Not Applicable	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Engline					
Oil Service		96742 Km	Dip Stick	No Visible Leaks	•
Oil Filter	No Visible Leaks	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	-	Fan Belt	Not Applicable	•
Air Filter	Good Condition	•	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Good Condition	•	Alternator Belt	Not Applicable	•
Spark Plugs	Good Condition	-	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	•	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	•	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Good Condition	-
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	60%	-
Front Brake Discs	Good Condition	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Good Condition	•
Rear Drums	Good Condition	-
Rear Linings	40%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	No Visible Leaks	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Visible Leaks	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	-
Turbo	Not Applicable	•
Injectors	No Visible Leaks	•
Fuel Pump	No Visible Leaks	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Good Condition	-
Glow Plugs	Not Applicable	•
Distrubutor	Good Condition	-
HT Leads	Good Condition	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Not Applicable	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	•
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	-
Handling	Good Condition	~

Concluding Remarks

Bosch Technician

NEW Technician

JOHN TSIPA

-Select-

General Comments

Date of Inspection

27-Nov-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

