

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-16 08:25:11
Technician Name: Christiaan
Order no:
Service fee:
Notes:

Vehicle Information

Make: BENZ
Model: 177.146 - A 250
VIN: W1K1771462J302453
Displacement: D 1.6 TCI-U2
Odometer: 62751 km
Vehicle Software Version: V10.84

Inspection Result

Driver-side SAM - Front Signal Acquisition And Actuation Module 1 problems exist

1.B1F4500 The starter battery has excessive resistance._ N/A

The following systems are OK:

- 1.PTCU - Drivetrain
- 2.FSCU - Fuel Pump
- 3.ME - Motor Electronics(Engine Control Module - ECM)
- 4.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 5.N68 - Electrical Power Steering (ES)
- 6.ESP - Electronic Stability Program
- 7.MFK - Multifunction Camera
- 8.PTS - PARKTRONIC
- 9.SG_AWF - COLLISION PREVENTION ASSIST
- 10.RDK - Tire Pressure Monitor
- 11.AML - Ambiance Light
- 12.ATA - Interior Motion Sensor
- 13.EIS/EZS - Electronic Ignition Lock
- 14.SG-SW_L - Left Headlamp
- 15.SG-SW_R - Right Headlamp
- 16.LRE - Steering Wheel Electronics
- 17.SCM - Steering Column Module
- 18.SD - Sliding Roof/Panoramic Sliding Sunroof
- 19.AB - Supplemental Restraint System

- 20.Control Unit For Telematics Services
- 21.ZAN - Audio/COMAND Display
- 22.Audio - Audio Or COMAND
- 23.IC - Instrument Cluster
- 24.TPAD - Touchpad
- 25.MTAS - Mobile Phone Cradle
- 26.DCU-LF - Left Front Door
- 27.DCU-RF - Right Front Door
- 28.AAC - Air Conditioning
- 29.LIN: H3/1 - Alarm siren (AS)
- 30.LIN: A67 - Dimming inside rearview mirror(AISP)
- 31.LIN: N70 - Overhead control panel(OCP)
- 32.LIN: M6/1 - Windowshield wiper(Windshield wiper FSW)
- 33.LIN: B95 - Battery sensor(BSN)
- 34.LIN: B38/2 - Rain/light sensor(RGLS)
- 35.LIN: N69/3 - Left rear door(DCU-LR)
- 36.LIN: N69/4 - Right rear door(DCU-RR)