

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 18208

Make	RENAULT
Model	SANDERO 900 T DYNAMIQUE
Vin	VF15SRAA450607452
Engine Specifications	Petrol
Vehicle Type	H/B
Service Plan	N/A

Year	2014
Km	150304
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Good Condition	-

### **BOSCH VEHICLE INSPECTION**

Linginio					
Oil Service		150314 Km	Dip Stick	No Visible Leaks	-
Oil Filter	No Visible Leaks	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable	•
Air Filter 0	Good Condition	•	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Good Condition	•	Alternator Belt	Not Applicable	•
Spark Plugs	Good Condition	•	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	•	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	•	Multi V belt	Not Applicable	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Good Condition	-
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Not Applicable	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Good Condition	•
Rear Drums	Good Condition	<b>~</b>
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Visible Leaks	-
Aircon Condensor	No Visible Leaks	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Good Condition	-
HT Leads	Good Condition	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	-
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	-
Shock Mountings Front	Good Condition	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Not Applicable	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Good Condition	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	-

Ignition System		
Diagnostics	Good Condition	•
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	-

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

JOHN TSIPA

-Select-

### General Comments

Date of Inspection

17-Jan-2025



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

