

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 13575

Make	VOLKSWAGEN		
Model	CADDY4 CREWBUS 2.0 TDi		
Vin	WV2ZZZ2KZJX10	09156	
Engine Specifications	2.0	Petrol	•
Vehicle Type	MPV		
Service Plan	N/A		

Year	2018
Km	156421
Transmission	Manual
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Good Condition	•

## **BOSCH VEHICLE INSPECTION**

21181110				
Oil Service		156421 Km	Dip Stick	Good Condition
Oil Filter	Good Condition	•	Oil Filler Cap	Good Condition
Fuel/Diesel Filter	Good Condition	•	Fan Belt	Good Condition
Air Filter	Good Condition	•	Fan belt Tensioner	Good Condition
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition
Spark Plugs	Not Applicable	•	Power Steering Belt	Not Applicable
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition
Antifreeze	Good Condition	•	Multi V belt	Good Condition
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition



Braking	System
	- ,

Front Brake Pads	-Select-	•
Front Brake Discs	Good Condition	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Good Condition	•
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	-
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Good Condition	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Good Condition	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	-
Gearbox	Good Condition	-
Gear & Diff oil	Good Condition	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	-
Cyl Leakage Test	Not Applicable	-
Road Test	Good Condition	-
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

-Select-

### General Comments

Date of Inspection

17-May-2024



HENDRIE

## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

