

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16426

Make	ΤΟΥΟΤΑ	
Model	FORTUNER 3.0D-4D	R/B
Vin	AHTZZ69G10502691	9
Engine Specifications	3.0	Diesel
Vehicle Type	SUV	
Service Plan	N/A	

Year	2012
Km	231687
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	•

## **BOSCH VEHICLE INSPECTION**

Oil Service		Km	Dip Stick	No Visible Leaks	•
Oil Filter	Not Applicable	-	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks	•	Fan Belt	Not Applicable	-
Air Filter	Good Condition	-	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Good Condition	-	Alternator Belt	Not Applicable	•
Spark Plugs	Not Applicable	-	Power Steering Belt	Not Applicable	•
Brake Fluid	Not Applicable	-	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	-	Multi V belt	Not Applicable	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Not Applicable	-
Sump/Gasket	Not Applicable	-	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	80%	-
Front Brake Discs	Good Condition	-
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Good Condition	•
Rear Drums	Good Condition	•
Rear Linings	60%	•
Brake Master	Good Condition	-
Hand Brake	Good Condition	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Visible Leaks	-
Aircon Condensor	No Visible Leaks	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	Good Condition	-
Turbo	Good Condition	-
Injectors	No Visible Leaks	•
Fuel Pump	No Visible Leaks	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Good Condition	•
Distrubutor	Good Condition	•
HT Leads	Good Condition	•



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	-
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	Not Applicable	-
Propshaft	Good Condition	•
Wheel Nuts/Studs	Good Condition	-
Tyres & Spare	Good Condition	-
Mag Wheels/Hub Caps	Not Applicable	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	•
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	-

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

JOHN TSIPA

-Select-

### General Comments

Date of Inspection

11-Oct-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

