

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: juan-dre@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-09-03 07:41:14  
Technician Name: Riaan  
Customer Name: citton cars  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Make: BENZ  
Model: 176.003 - A 220 CDI  
VIN: WDD1760032J444090  
Displacement: G 1.2 MPI KAPPA  
Odometer: 96163 km  
Vehicle Software Version: V10.74

## Inspection Result

The following systems are OK:

1. CDI - Engine Control Module (ECM)
2. FSCU\_EC - Control Unit 'Fuel pump' (N118)
3. ETC/VGS - Transmission Control Module (TCM)
4. CPF - Camera Cover
5. PTCU - Drivetrain
6. EPB - Electrical Parking Brake (EPB)
7. ESP - Electronic Stability program (N30/4)
8. ES - Electrical Power Steering (N68)
9. TPC - Tire Pressure Monitoring System (TPMS) (N88)
10. EIS/EZS - Electronic Ignition lock (N73)
11. SG\_AWF - Control Unit 'COLLISION PREVENTION ASSIST' (A90)
12. SAM - Signal Acquisition And Actuation module (N10)
13. AB - Supplemental Restraint system (N2/10)
14. RevGUS\_VL - Left Front Reversible Emergency Tensioning retractor (A76)
15. RevGUS\_VR - Right Front Reversible Emergency Tensioning retractor (A76/1)
16. ATA - ATA [EDW] / tow-away Protection / Interior protection (N26/6)
17. RFK - Backup camera (B84/3)
18. IC - Instrument cluster (A1)
19. SCCM - Steering Column module (N80)
20. PTS - PARKTRONIC (N62)
21. ZBE - Operating Unit Of Control Unit 'Audio Or COMAND' (A40/9)

- 22.ZAN - Audio/COMAND display(A40/8)
- 23.Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
- 24.DCU\_LF - Left Front door(N69/1)
- 25.DCU\_RF - Right Front door(N69/2)
- 26.AC - Air Conditioning(N22/7)
- 27.LIN: N70 - Overhead control panel(OCP)
- 28.LIN: B95 - Battery sensor(BSN)
- 29.LIN: B38/2 - Rain/light sensor(RGLS)
- 30.LIN: N72/1 - Upper control panel(UCP)
- 31.LIN: H3/1 - Alarm siren (AS)