

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: Bosch Car Service Pretoria

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 2023-12-01 15:45:55

Technician Name: Lu-André

Vehicle Information

Make: BENZ

Model: 176.008 - A 200 CDI

VIN: WDD1760082J542979

Displacement: G 1.2 MPI

Odometer: 117947 km

Vehicle Software Version: V10.54

Inspection Result

The following systems are OK:

1. ECM - Engine Control Module(CDI)
2. FSCU_EC - Control Unit 'Fuel pump'(N118)
3. TCM - Transmission Control Module
4. PTCU - Drivetrain
5. EPB - Electrical Parking Brake
6. ESP - Electronic Stability program(N30/4)
7. EPS - Electrical Power Steering(N68)
8. TPMS - Tire Pressure Monitoring System(N88)
9. EZS - Electronic Ignition lock(N73)
10. SG-AWF - Control Unit 'Distance Warning function'(A90)
11. SAM - Signal Acquisition And Actuation module(N10)
12. LIN bus: N70 - Overhead control panel(OCP)
13. LIN bus: B95 - Battery sensor(BSN)
14. LIN bus: B38/2 - Rain/light sensor(RGLS)
15. LIN bus: N72/1 - Upper control panel(UCP)
16. SRS - Supplemental Restraint system(N2/10)
17. ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)
18. LIN bus: H3/1 - Alarm siren (AS)
19. IC - Instrument cluster(A1)
20. SCCM - Steering Column module(N80)
21. PTS - PARKTRONIC(N62)
22. ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)
23. ZAN - Audio/COMAND display(A40/8)
24. Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
25. DCU_LF - Left Front door(N69/1)