

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-03-19 07:39:28
Technician Name:Basal
Customer Name:bosch

Vehicle Information

Make:BENZ
VIN:WDD1760432J517678
Odometer:97265 km
Vehicle Software Version:V10.74

Inspection Result

The following systems are OK:

- 1.ME - Motor electronics(Engine Control Module - ECM)
- 2.FSCU - Control Unit 'Fuel pump'(N118)
- 3.ETC/VGS - Transmission Control Module(TCM)
- 4.EPB - Electrical Parking Brake(EPB)
- 5.ESP - Electronic Stability program(N30/4)
- 6.ES - Electrical Power Steering(N68)
- 7.TPC - Tire Pressure Monitoring System(TPMS)(N88)
- 8.EIS/EZS - Electronic Ignition lock(N73)
- 9.SG_AWF - Control Unit 'COLLISION PREVENTION ASSIST'(A90)
- 10.SAM - Signal Acquisition And Actuation module(N10)
- 11.AB - Supplemental Restraint system(N2/10)
- 12.RevGUS_VL - Left Front Reversible Emergency Tensioning retractor(A76)
- 13.RevGUS_VR - Right Front Reversible Emergency Tensioning retractor(A76/1)
- 14.ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)
- 15.SG-SW_L - Left Headlamp
- 16.SG-SW_R - Right Headlamp
- 17.MFK - Multifunction camera(A40/11)
- 18.IC - Instrument cluster(A1)
- 19.SCCM - Steering Column module(N80)
- 20.PTS - PARKTRONIC(N62)
- 21.ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)
- 22.ZAN - Audio/COMAND display(A40/8)
- 23.Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
- 24.DCU_LF - Left Front door(N69/1)
- 25.DCU_RF - Right Front door(N69/2)
- 26.AC - Air Conditioning(N22/7)

- 27.LIN: N70 - Overhead control panel(OCP)
- 28.LIN: B95 - Battery sensor(BSN)
- 29.LIN: B38/2 - Rain/light sensor(RGLS)
- 30.LIN: N72/1 - Upper control panel(UCP)
- 31.LIN: H3/1 - Alarm siren (AS)