

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:2024-03-25 15:36:02  
Technician Name:Basal  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Make:SPRINTER  
Model:VITO/V/Metris - Cla  
VIN:WDF44760323499384  
Displacement:G 1.2 MPI KAPPA  
Odometer:110731 km  
Vehicle Software Version:V10.26

## Inspection Result

ESP - Electical Stabillity Program 1 problems exist

1.C066300 CAN Signal "Accept Phone Call / Voice Control System" From Control Unit "User Interface CAN Bus" Is Missing Or Implausible.

CURRENT And STORED

The following systems are OK:

- 1.ECM - Engine Control Module
- 2.FSCU - Control Unit 'Fuel Pump'
- 3.ES - Electrical Power Steering
- 4.SAM - Signal Acquisition And Actuation Module
- 5.EZS - Electronic Ignition Lock
- 6.SRS - Supplemental Restraint System
- 7.SCM - Steering Column Module
- 8.IC-Instrument Cluster
- 9.DCU - LF - Left Front Door
- 10.DCU - RF - Right Front Door
- 11.AAC - Air Conditioning