

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/02/2024 10:38:22

Technician Name:Wimpie F

## Vehicle Information

Make:BENZ

Model:176.008 - A 200 CDI

VIN:WDD1760082J765839

Displacement:D 1.4 TCI-U2

Odometer:122534 km

Vehicle Software Version:V10.88

## Inspection Result

The following systems are OK:

- 1.CDI - Engine Control Module(ECM)
- 2.FSCU\_EC - Control Unit 'Fuel pump'(N118)
- 3.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 4.CPF - Camera Cover
- 5.PTCU - Drivetrain
- 6.EPB - Electrical Parking Brake(EPB)
- 7.ESP - Electronic Stability program(N30/4)
- 8.ES - Electrical Power Steering(N68)
- 9.TPC - Tire Pressure Monitoring System(TPMS)(N88)
- 10.EIS/EZS - Electronic Ignition lock(N73)
- 11.ABA - Active Brake Assist (A108))
- 12.SAM - Signal Acquisition And Actuation module(N10)
- 13.AB - Supplemental Restraint system(N2/10)
- 14.ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)
- 15.SG-SW\_L - Left Headlamp
- 16.SG-SW\_R - Right Headlamp
- 17.KG - KEYLESS GO(N69/5)
- 18.SD - Sliding Roof/Panoramic Sliding Sunroof
- 19.Control Unit For Telematics Services
- 20.MFK - Multifunction camera(A40/11)
- 21.RFK - Backup camera(B84/3)
- 22.IC - Instrument cluster(A1)
- 23.SCCM - Steering Column module(N80)
- 24.PTS - PARKTRONIC(N62)
- 25.ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)

- 26.ZAN - Audio/COMAND display(A40/8)
- 27.Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
- 28.DCU\_FL - Left Front door(N69/1)
- 29.DCU\_FR - Right Front door(N69/2)
- 30.AC - Air Conditioning(N22/7)
- 31.LIN: N70 - Overhead control panel(OCP)
- 32.LIN: B95 - Battery sensor(BSN)
- 33.LIN: B38/2 - Rain/light sensor(RGLS)
- 34.LIN: N72/1 - Upper control panel(UCP)
- 35.LIN: H3/1 - Alarm siren (AS)