

Diagnostic Report

THINKCAR

Time: 09/16/2024 11:12:24

Customer Name: citton cars

Technician Name: Riaan

| | |
|-----------------------------|----------------|
| Shop Name: N/A | Telephone: N/A |
| Email: jaco@boschgezina.co. | Country: N/A |
| State: N/A | City: N/A |
| Address1: N/A | Address2: N/A |

| | |
|------------------------|----------------------------------|
| Make: BMW | Model: X1 sDrive20d |
| Year: 2019.02 | Displacement: G 1.4 MPI KAPPA |
| VIN: WBAHU120905L71068 | Odometer: 99388 km |
| License #: N/A | Vehicle Software Version: V10.44 |

Pre-Scan

09/16/2024 11:12:24

| System(19) | Status |
|---|----------|
| CAS/BDC/FEM (Car Access System/Body domain controller/Front Electronics Module) | No Fault |
| DME/DDE (Digital Motor Electric - ECM) | No Fault |
| DSC (Dynamic Stability Control - ABS) | No Fault |
| EPS (Electronic Power Steering) | No Fault |
| ACSM (Advanced Crash Safety Module(SRS)) | No Fault |
| ZGM (Central Gateway Module) | No Fault |
| PMA (Parking Assistant) | No Fault |
| AMPT (Amplifier) | No Fault |
| LHML/FLEL (LED Main Light Module, Left) | No Fault |

| | |
|--|----------|
| LHMR/FLER (LED Main Light Module, Right) | No Fault |
| FZD (Function Center, Roof) | No Fault |
| KOMBI (Instrument Cluster) | No Fault |
| HU-H/HU-B/CIC (Head Unit High) | No Fault |
| CON (Controller) | No Fault |
| IHKA (Air Conditioning) | No Fault |
| EGS (Transmission Control Module - TCM) | No Fault |
| TRSVK (All Round View Camera) | No Fault |
| HKFM (Tailgate Function Module) | No Fault |
| TCB (Telematic communication box) | No Fault |