

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:2024-06-20 15:14:19
Technician Name:Raymond
Order no:
Service fee:
Notes:

Vehicle Information

Make:BENZ
VIN:WDD1173432N674697
Displacement:G 1.6 MPI
Odometer:78146 km
Vehicle Software Version:V10.76

Inspection Result

The following systems are OK:

- 1.FSCU - Fuel Pump
- 2.ME - Motor electronics(Engine Control Module - ECM)
- 3.Y3/8 - Transmission control for 9-speed transmission(VGS)
- 4.EFB - Electrical Parking Brake(EPB)
- 5.ES - Electronic Power Steering
- 6.ESP - Electronic Stability Program
- 7.TPC - Tire Pressure Monitoring System(TPMS)
- 8.SG_AWF - COLLISION PREVENTION ASSIST
- 9.EIS/EZS - Electronic Ignition Lock
- 10.ATA - Interior Motion Sensor
- 11.MFK - Multifunction Camera
- 12.SCM - Steering Column Module
- 13.SD - Sliding Roof/Panoramic Sliding Sunroof
- 14.RFK - Backup Camera
- 15.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 16.AB - Supplemental Restraint System(SRS)
- 17.SG-SW_L - Left Headlamp
- 18.SG-SW_R - Right Headlamp
- 19.KG - Keyless GO
- 20.CPF - Camera Cover
- 21.Audio - Audio Or COMAND
- 22.IC - Instrument Cluster
- 23.PTS - PARKTRONIC

- 24.ZAN - Audio/COMAND Display
- 25.COU[ZBE] - Audio/COMAND Operating Unit
- 26.Control Unit For Telematics Services
- 27.SG-MSND - Engine Sound
- 28.DCU_LF - Left Front Door
- 29.DCU_RF - Right Front Door
- 30.AC - Air Conditioning
- 31.LIN: H3/1 - Alarm siren (AS)
- 32.LIN: N70 - Overhead control panel(OCP)
- 33.LIN: B95 - Battery sensor(BSN)
- 34.LIN: B38/2 - Rain/light sensor(RGLS)
- 35.LIN: N72/1 - Upper control panel(UCP)