



Vehicle Information

Brand: BENZ VIN: WDD1770462N094634 Plate Number:
Model: A (177) Mileage: 42437 km Color:
Year: Capacity: Status: Unset status
Engine: 260.920 Reference: Date: 18.11.2024 09:21:01

Automatic scanning results

System Name	Status/Count
01-ME-Engine electronics	Pass No Fault
02-VGS-Transmission control	Pass No Fault
03-ESP-Electronic stability program	Pass No Fault
04-SRS-Supplemental restraint system	Pass No Fault
05-KI-Instrument cluster	Pass No Fault
06-FSCU-Control unit 'Fuel pump'	Pass No Fault
07-PTCU-Control unit 'Drivetrain'	Pass No Fault
08-ES-Electrical power steering	Pass No Fault
09-SAMF-Front signal acquisition and actuation module	Fault 1
10-EZS-Electronic ignition lock	Pass No Fault
11-KLA-Air conditioningControl unit	Pass No Fault
12-DMFL-Left front door	Pass No Fault
13-DMFR-Right front door	Pass No Fault
14-ATA-Interior motion sensor	Pass No Fault



15-PSD-Control module 'Sliding roof'	Pass No Fault
16-AML-Ambiance light	Pass No Fault
17-LRE-Steering wheel electronics	Pass No Fault
18-SG-SW-L-Left headlamp	Pass No Fault
19-SG-LML-VL-LED matrix of left front lamp unit	Pass No Fault
20-SG-SW-R-Right headlamp	Pass No Fault
21-SG-LML-VR-LED matrix of right front lamp unit	Pass No Fault
22-MRM-Steering column module	Pass No Fault
23-TPM-Tire pressure monitor	Pass No Fault
24-PTS-Control unit 'PARKTRONIC'	Pass No Fault
25-MMPC-Multifunction camera (mono)	Pass No Fault
26-SG-AWF-COLLISION PREVENTION ASSIST	Pass No Fault
27-HERMES-Control unit for telematics services	Pass No Fault
28-TPAD-Touchpad	Pass No Fault
29-HU-Audio or COMAND	Pass No Fault
30-ZAN-Audio/COMAND display	Pass No Fault
31-LIN Bus : BSN-Battery sensor	Pass No Fault
32-LIN Bus : FSW-Windshield wiper	Pass No Fault
33-LIN Bus : RGLS-Rain/light sensor	Pass No Fault
34-LIN Bus : DBE-Control unit 'Overhead control panel'	Pass No Fault
35-LIN Bus : AISP-Dimming inside rearview mirror	Pass No Fault
36-LIN Bus : AS-Alarm siren	Pass No Fault



37-LIN Bus : DMRL-Left rear door Pass | No Fault

38-LIN Bus : DMRR-Right rear door Pass | No Fault

39-LIN Bus : KLA-F-Front air conditioning system Switch panel Pass | No Fault

SAMF-Front signal acquisition and actuation module

ID	Status	Description
U014341	Stored&Current	Communication with the multifunction control unit has a malfunction. There is a general checksum error.

Contact Information

Name:

Address: Pretoria Gauteng

Phone:

Email:

Website: