

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Sn: 988579800333  
Time: 11/13/2024 09:46:57  
Technician Name: Dries

## Vehicle Information

Year: 2019  
Make: PEUGEOT  
Model: 208  
VIN: VF3CCHMZ0KW096033  
Displacement: G 1.0 T-GDI KAPPA  
Odometer: 110700 km  
Vehicle Software Version: V10.38

## Inspection Result

Built-in Systems Interface(Bsi) 2 problems exist

- |   |           |
|---|-----------|
| 1.B1418 Fault In The Status Of The Seat Belt Fastening Information For Determining The Presence Of The Driver | Permanent |
| 2.B1003 Configuration Fault   | Permanent |

The following systems are OK:

- 1.Engine ECU
- 2.Anti-lock Braking System (ABS) Or Electric Stability Program (ESP)
- 3.Airbag
- 4.Air Conditioning
- 5.Rain And Brightness Sensor
- 6.Instrument Panel
- 7.Steering Wheel With Integral Controls
- 8.Battery Charge Status Unit
- 9.Audio-navigation Or Telematic Unit Or Connected Audio System
- 10.Intrusion Alarm Siren
- 11.Anti-theft Alarm
- 12.Switch Module Under The Steering Wheel
- 13.Electric Power Steering
- 14.Multiplexed Control Panel