

Diagnostic Report

THINKCAR

Time: 01/07/2025 11:34:29

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Menlyn	Telephone: N/A
Email: Mike	Country: South Africa
State: Gauteng	City: Pretoria
Address1: 109 Atterbury ave	Address2: N/A

Make: BENZ	Model: 177.087 - A 200
Year: N/A	Displacement: G 1.0 T-GDI KAPPA
VIN: WDD1770872N025071	Odometer: 95668 km
License #: N/A	Vehicle Software Version: V10.98

Pre-Scan

01/07/2025 11:34:29

System(36)	Status(2)
PTCU - Drivetrain	No Fault
FSCU - Fuel Pump	No Fault
SG_EM - Power Electronics	No Fault
ME - Motor Electronics(Engine Control Module - ECM)	No Fault
VGS/DKG/DCT - Transmission Control Unit (TCM)	No Fault
N68 - Electrical Power Steering (ES)	No Fault
ESP - Electronic Stability Program	No Fault
MFK - Multifunction Camera	No Fault
PTS - PARKTRONIC	No Fault
SG_AWF - COLLISION PREVENTION ASSIST	No Fault

Mercedes-Benz Intelligent Drive	No Fault
RDK - Tire Pressure Monitor	No Fault
ATA - Interior Motion Sensor	Fault 1
EIS/EZS - Electronic Ignition Lock	No Fault
SG-SW_L - Left Headlamp	No Fault
SG-SW_R - Right Headlamp	No Fault
LRE - Steering Wheel Electronics	No Fault
SCM - Steering Column Module	No Fault
Driver-side SAM - Front Signal Acquisition And Actuation Module	No Fault
AB - Supplemental Restraint System	No Fault
Control Unit For Telematics Services	No Fault
ZAN - Audio/COMAND Display	No Fault
Audio - Audio Or COMAND	No Fault
IC - Instrument Cluster	No Fault
TPAD - Touchpad	No Fault
DCU-LF - Left Front Door	No Fault
DCU-RF - Right Front Door	No Fault
AAC - Air Conditioning	No Fault
LIN: H3/1 - Alarm siren (AS)	Fault 1
LIN: A67 - Dimming inside rearview mirror(AISP)	No Fault
LIN: N70 - Overhead control panel(OCP)	No Fault
LIN: M6/1 - Windowshield wiper(Windshield wiper FSW)	No Fault
LIN: B95 - Battery sensor(BSN)	No Fault
LIN: B38/2 - Rain/light sensor(RGLS)	No Fault
LIN: N69/3 - Left rear door(DCU-LR)	No Fault

LIN: N69/4 - Right rear door(DCU-RR)

No Fault

DTC

System	Code	Description	Status
ATA - Interior Motion Sensor	B225397	The alarm siren has a malfunction.The system function is restricted.	CURRENT and STORED
LIN: H3/1 - Alarm siren (AS)	B225397	The alarm siren has a malfunction.The system function is restricted.	CURRENT and STORED