

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-10-02 08:29:16

Technician Name:Dries

Order no:

Service fee:

Notes:

Vehicle Information

Year:2021

Make:USAFORD

Model:EcoSport

VIN:MAJAXXMRKAMJ00115

Displacement:G 1.2 MPI KAPPA

Odometer:48213 km

Vehicle Software Version:V10.86

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Brake System)
- 2.ACM (Audio Front Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCM (Body Control Module)
- 5.GWM (Gateway Module A)
- 6.HVAC (Heating, Ventilation And Air Conditioning)
- 7.IPC (Instrument Panel Cluster)
- 8.PAM (Parking Assist Control Module)
- 9.PCM (Powertrain Control Module)
- 10.PSCM (Power Steering Control Module)
- 11.RCM (Restraints Control Module)
- 12.SCCM (Steering Column Control Module)