

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-07-06 08:52:43

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Year:2018

Make:CHANGCHENG

Model:HAVAL H9 2019-2022(8

VIN:LGWFF8A64JH905992

Odometer:118279 km

Vehicle Software Version:V10.32

Inspection Result

RHVSM(Rear Heat Vent Seat Module)(Big Five Seats Back Row Or Seven Seats Second Row) 2 problems exist

1.11,A1,89,71 Please refer to manual

2.11,A1,89,71 Please refer to manual

Current DTC

History DTC

The following systems are OK:

1.ECM (Engine Control Module)

2.SBWM (Shifting By Wire Module)

3.Left Radar Side Detection System(RSDS-L)

4.Right Radar Side Detection System(RSDS-R)

5.ELD (Electronic Differential Lock)

6.HVSM(Heat Vent Seat Module)