Fault Code Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre Address:564 Steve Biko Road Telephone:0123355737 Email:johan@boschgezina.co.za Sn:988579800333 Time:2024-09-03 14:56:50 Technician Name:Christiaan Order no: Service fee: Notes:

.

Vehicle Information

Year:2017 Make:VW VIN:AAVZZZ6RZHU066218 Odometer:140771 km Vehicle Software Version:V10.23

Inspection Result

.

| | Inop decion Rebuild | |
|--|--------------------------|---------------|
| 09 Electronic Central Electric 2 problems | s exist | |
| 1.B12E815 Left Side Marker Lamp Bul Circuit To B+ | b - Open Circuit/Short | Active/Static |
| 2.B12E915 Right Side Marker Lamp Bu Circuit To B+ | ılb - Open Circuit/Short | Active/Static |