

Diagnostic Report

THINKCAR

Time: 01/24/2025 13:37:51

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Menlyn	Telephone: N/A
Email: Mike	Country: South Africa
State: Gauteng	City: Pretoria
Address1: 109 Atterbury ave	Address2: N/A

Make: KIA	Model: Picanto/Morning(JA)
Year: 2021	Displacement: G 1.0 MPI KAPPA
VIN: KNAB2511LMT808070	Odometer: 0 miles
License #: KN86MVGP	Vehicle Software Version: V10.50

Pre-Scan

01/24/2025 13:37:51

System(10)	Status
ECM (Engine Control Module)	No Fault
ABS/ESP	No Fault
Airbag(Event #1)	No Fault
Airbag(Event #2)	No Fault
AC (Air Conditioning)	No Fault
BCM (Body Control Module)	No Fault
IC (Instrument Cluster)	No Fault
TPMS (Tire Pressure Monitoring System)	No Fault
MDPS (Motor Driven Power Steering)	No Fault
CODE (Transmitter Code Saving)	No Fault

