

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-05-27 08:25:01
Technician Name: Dries
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2017
Make: KIA
Model: Sportage(QLE)
VIN: U5YPH813MHL308411
Displacement: D 2.0 TCI R
Odometer: 99690 km
Vehicle Software Version: V10.38

Inspection Result

BCM (Body Control Module) 4 problems exist

1. B121400 Rear Left Sensor Fault	Present
2. B121500 Rear Center Left Sensor Fault	Present
3. B121600 Rear Center Right Sensor Fault	Present
4. B121700 Rear Right Sensor Fault	Present

The following systems are OK:

1. ECM (Engine Control Module)
2. TCM (Transmission Control Module)
3. ESP (Electronic Stability Program)
4. Airbag (Event #1)
5. Airbag (Event #2)
6. AC (Air Conditioning)
7. IC (Instrument Cluster)
8. SJB (Smart Junction Block)
9. Motor Driven Power Steering (Mando C-Type)
10. Motor Driven Power Steering (Mando R-Type)
11. Smart Key Unit
12. CODE (Transmitter Code Saving)