Make	VOLKSWAGEN		
Model	POLO 1.0 TSI TRENDLINE		
Vin	AAVZZZAWZLU0085	25	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2019
Km	115704
Transmission	Manual
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	-	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	—	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	—
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	~
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	•
Antifreeze	Good Condition		Multi V belt	No Cracks	~
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	40%	•
Brake Master	No Visible Leaks	
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	_
Waterpump	Good Condition	_
Thermostat	Good Condition	•
Aircon Gas	No Visible Leaks	
Aircon Pump	No Fault Code	
Aircon Condensor	No Visible Leaks	_
Interior Fan	No Fault Code	_
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	No Fault Code	~
Turbo	No Fault Code	~
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	~

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	~
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	No Visible Leaks	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	\
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	—
Wheel Nuts/Studs	Within Specification	T
Tyres & Spare	Within Specification	—
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	lacksquare
Clutch Slave	No Visible Leaks	V
Clutch Cable	Not Applicable	V
Gearbox	No Visible Leaks	V
Gear & Diff oil	No Visible Leaks	lacksquare
Auto Transmission	Not Applicable	lacksquare
Gear Selector	Within Specification	lacksquare
Gear Linkages	Within Specification	▼

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



