

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-06-28 16:18:47

Technician Name:shaun

Order no:

Service fee:

Notes:

Vehicle Information

Year:2017

Make:USAFORD

Model:Focus C-MAX

VIN:WF05XXGCC5HK09103

Displacement:G 1.6 DOHC

Odometer:96351 km

Vehicle Software Version:V10.76

Inspection Result

BCMII (Body Control Module) 1 problems exist

1.B1D00:15-2F Left Low Beam

Continuous Memory DTCs

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.FCDIM (Front Control/Display Interface Module)
- 5.GPSM (Global Positioning System Module)
- 6.IPC (Instrument Panel Control Module)
- 7.PCM (Powertrain Control Module)
- 8.PSCM (Power Steering Control Module)
- 9.RCM (Restraint Control Module)
- 10.SASM (Steering Angle Sensor Module)