

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-08-12 14:08:34

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Make:RENAULT

Model:TRIBER

VIN:MEERBC00800145936

Displacement:G 2.0 NU MPI

Odometer:49667 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.IC (Instrument Cluster)
- 4.UCH
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.Variable P.A.S