Make	ТОУОТА	
Model	YARIS 1.5 XS CVT 5Dr	
Vin	MR2K29F370112162	2
Engine Specifications	1.5	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2018
Km	85482
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	~	Aircon Controls	Within Specification	_
Cluster	Within Specification	—	Electric Windows	Within Specification	_

Exterior					
Windscreen	Renewed	-	Mag Wheels	Within Specification	~
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Renewed	~

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		85518 Km	Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	lacksquare	Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	lacksquare	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	_	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	-	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	•
Rear Brake Discs	Within Specification	—
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	—
Brake Calipers	Within Specification	—
Brake Hose	Within Specification	—

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	—
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	—
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	—
Wheel Alignment	Within Specification	—
CV Joints	Within Specification	—
CV Boots	Within Specification	—
Shocks Front	Within Specification	—
Shock Mountings Front	Within Specification	—
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	—
Wheel Bearings	Within Specification	—
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	-
Sideshafts/Seal	No Visible Leaks	—
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Not Applicable	-
Tyres & Spare	Within Specification	-
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	~
Clutch Cable	Not Applicable	~
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	-
Auto Transmission	Within Specification	-
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Elias Makubela	
NEW Technician	Date of Inspection



