

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co

Sn: 988579800333

Time: 2024-07-16 14:19:12

Technician Name: Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Make: BENZ

VIN: WDD2050402R421657

Odometer: 95926 km

Vehicle Software Version: V10.76

Inspection Result

ME - Motor electronics (Engine Control Module - ECM) 1 problems exist

1.P13B011 The output for on-board electrical system switchover STORED has a short circuit to ground. There is a short circuit to ground.

The following systems are OK:

- 1.PTCU - Common Powetrain Controller
- 2.FSCU - Fuel Pump
- 3.Y3/8 - Transmission control for 9-speed transmission(VGS)
- 4.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 5.B95 (Battery sensor)
- 6.B38/2 (Rain/light sensor with additional functions)
- 7.N70 (Overhead control panel control unit)
- 8.Windshield wiper
- 9.REAR SAM - Rear Signal Acquisition And Actuation Module
- 10.EIS/EZS - Electronic Ignition Lock
- 11.SG-SW_L - Left Headlamp
- 12.SG-SW_R - Right Headlamp
- 13.AB - Supplemental Restraint System
- 14.SCM - Steering Column Module
- 15.SD - Control Module Sliding Roof
- 16.ATA - Interior Motion Sensor
- 17.LIN bus: AS - Alarm Siren
- 18.PTS - PARKTRONIC
- 19.RFK - Backup Camera
- 20.TPC - Tire Pressure Monitoring System (TPMS)
- 21.ES - Electrical Power Steering

- 22.ESP - Electronic Stability Program
- 23.KAB - Camera Cover(N42)
- 24.COU[ZBE] - Audio/COMAND Operating Unit
- 25.N72/1 (Upper control panel control unit)
- 26.N72/4 (Left lower control panel)
- 27.N72/5 (Right lower control panel)
- 28.ZAN - Audio/COMAND Display
- 29.Control Unit For Telematics Services
- 30.Audio - Audio Or COMAND
- 31.IC - Instrument Cluster
- 32.TPAD - Touchpad
- 33.AC - Air Conditioning
- 34.DCU-LF - Left Front Door
- 35.DCU_RF - Right Front Door
- 36.DCU-LR - Left Rear Door
- 37.DCU-RR - Right Rear Door