

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 16890

Make	MITSUBISHI		
Model	PAJERO SPORT 2.5D 4X4 A/T		
Vin	MMBGYKH40EF0234	33	
Engine Specifications	2.5	Diesel	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2016
Km	154150
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION

8				
Oil Service		154150 Km	Dip Stick	Within Specification
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification
Spark Plugs	Within Specification	•	Power Steering Belt	Within Specification
Brake Fluid	Within Specification	•	Aircon Belt	Within Specification
Antifreeze	Within Specification	•	Multi V belt	Within Specification
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification

BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	80%	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	100%	-
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	-
Rear Linings	80%	•
Brake Master	Within Specification	-
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	-
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	-
CV Boots	Within Specification	•
Shocks Front	Within Specification	-
Shock Mountings Front	Within Specification	-
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

