

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 10/31/2024 07:37:15
Technician Name: Elias

Vehicle Information

Year: 2015
Make: USAFORD
Model: EcoSport
VIN: MAJAXXMRKAFM25086
Odometer: 98489 miles
Vehicle Software Version: V10.86

Inspection Result

RCM (Restraint Control Module) 5 problems exist

1.B0001:13-8B Driver's Frontal Stage 1 Deployment Control	Continuous Memory DTCs
2.B0010:13-8B Passenger's Frontal Stage 1 Deployment Control	Continuous Memory DTCs
3.B007E:13-8B Driver Safety Belt Pretensioner C Deployment Control	Continuous Memory DTCs
4.B007F:13-8B Passenger Safety Belt Pretensioner C Deployment Control	Continuous Memory DTCs
5.B1193:00-C0 Crash Event Storage Full And Locked	Continuous Memory DTCs

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.FCDIM (Front Control/Display Interface Module)
- 6.HVAC (Heating Ventilation Air Conditioning)
- 7.IPC (Instrument Panel Control Module)
- 8.PCM (Powertrain Control Module)
- 9.PSCM (Power Steering Control Module)