

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16697

Make	FORD		
Model	EVEREST 2.0D BI-TURBO XLT A/T		
Vin	AFAJXXMJWJLL2635	5	
Engine Specifications	2.0	Diesel	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2020
Km	102726
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Within Specification	•
Cluster	Good Condition	•	Electric Windows	Good Condition	<b>•</b>

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Not Applicable	•	Oil Filler Cap	Within Specification	-
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Within Specification	•
Air Filter	Not Applicable	-	Fan belt Tensioner	Within Specification	-
Cabin Filter	Not Applicable	-	Alternator Belt	Within Specification	•
Spark Plugs	Not Applicable	-	Power Steering Belt	Not Applicable	•
Brake Fluid	Not Applicable	•	Aircon Belt	Within Specification	•
Antifreeze	Not Applicable	•	Multi V belt	Not Applicable	•
Rear Main Seal	Not Applicable	-	Engine Mountings	Within Specification	-
Sump/Gasket	Not Applicable	•	PCV Valve	Within Specification	•

# BOSCH INSPECTION REPORT

E

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	40%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	-
Bearing Hubs	Within Specification	-
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Not Applicable	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

## Bosch Technician

**NEW Technician** 

-Select-

## General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

