

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: mariska@boschgezina.co.za  
Sn: 988579800333  
Time: 10/28/2024 09:26:00  
Technician Name: Juan-Dre

## Vehicle Information

Year: 2020  
Make: USAFORD  
Model: Everest  
VIN: AFAJXXMJWJLL26355  
Displacement: G 1.4 MPI KAPPA  
Odometer: 102741 miles  
Vehicle Software Version: V10.86

## Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Brake System)
2. ACM (Audio Front Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCM (Body Control Module)
5. DACMC (Digital Audio Control Module C)
6. DDM (Driver Door Module)
7. FCIM (Front Controls Interface Module)
8. GWM (Gateway Module A)
9. IPC (Instrument Panel Cluster)
10. PAM (Parking Assist Control Module)
11. PCM (Powertrain Control Module)
12. PDM (Passenger Door Module)
13. PSCM (Power Steering Control Module)
14. RCM (Restraints Control Module)
15. RHVAC (Rear Heating, Ventilation And Air Conditioning)
16. RTM (Radio Transceiver Module)
17. SCCM (Steering Column Control Module)
18. TCCM (Transfer Case Control Module)
19. TCM (Transmission Control Module)
20. TRM (Trailer Module)