

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-08-02 09:46:28

Technician Name:Lesego

Order no:

Service fee:

Notes:

Vehicle Information

Year:2012

Make:HYUNDAI

Model:Tucson/ix35(LM)

VIN:KMHJU81BLCU528889

Displacement:G 2.0 MPI

Odometer:140742 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM(Engine Control Module)-Leaded All
- 2.ECM(Engine Control Module)-Unleaded EOBD
- 3.ECM(Engine Control Module)-Unleaded GEN
- 4.ESP (Electronic Stability Program)
- 5.Airbag(Event #1)
- 6.Airbag(Event #2)
- 7.Air Conditioner(EURO)
- 8.Air Conditioner(GEN)
- 9.BCM (Body Control Module)
- 10.Smart Junction Block
- 11.IMM (Immobilizer)
- 12.Transmitter Code Saving