Make	VOLKSWAGEN		
Model	POLO VIVO GP 1.4 TRENDLINE		
Vin	AAVZZZ6SZHU030	285	
Engine Specifications	1.4	Petrol	
Vehicle Type	S/D		
Service Plan	N/A		

Year	2017
Km	132027
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	~

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	~	Wiper Blades	Good Condition	\rightarrow

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification		Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	-
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	-
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	-
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	_
Sump/Gasket	Good Condition		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	\rightarrow
Radiator Hoses	No Visible Leaks	—
Waterpump	No Visible Leaks	~
Thermostat	No Visible Leaks	_
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	V
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	-
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	—



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	-
Power Steering Pump	Not Applicable	lacksquare
Wheel Alignment	Within Specification	
CV Joints	Within Specification	lacksquare
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	lacksquare
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	-
Clutch Master	No Visible Leaks	-
Clutch Slave	No Visible Leaks	
Clutch Cable	Not Applicable	~
Gearbox	No Visible Leaks	~
Gear & Diff oil	No Visible Leaks	~
Auto Transmission	Not Applicable	~
Gear Selector	Within Specification	~
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	~
Road Test	Within Specification	-
Handling	Within Specification	T

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



