

Diagnostic Report

THINKCAR

Time: 09/23/2024 07:54:14

Customer Name: N/A

Technician Name: shaun

Shop Name: N/A	Telephone: N/A
Email: pieter	Country: N/A
State: N/A	City: N/A
Address1: N/A	Address2: N/A

Make: BENZ	Model: 246.243 - B 200
Year: N/A	Displacement: G 1.1 MPI
VIN: WDD2462432J308435	Odometer: 86938 km
License #: N/A	Vehicle Software Version: V10.84

Pre-Scan

09/23/2024 07:54:14

System(30)	Status
ME - MOTOR ELECTRONICS FOR COMBUSTION ENGINE(ECM)	No Fault
FSCU - Control Unit 'Fuel pump'(N118)	No Fault
VGS/DKG/DCT - Transmission Control Unit (TCM)	No Fault
EPB - Electrical Parking Brake(EPB)	No Fault
ESP - Electronic Stability program(N30/4)	No Fault
ES - Electrical Power Steering(N68)	No Fault
TPC - Tire Pressure Monitoring System(TPMS)(N88)	No Fault
EIS/EZS - Electronic Ignition lock(N73)	No Fault
ABA - Active Brake Assist (A108))	No Fault
SAM - Signal Acquisition And Actuation module(N10)	No Fault

AB - Supplemental Restraint system(N2/10)	No Fault
RevGUS_VL - Left Front Reversible Emergency Tensioning retractor(A76)	No Fault
RevGUS_VR - Right Front Reversible Emergency Tensioning retractor(A76/1)	No Fault
ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)	No Fault
KG - KEYLESS GO(N69/5)	No Fault
IC - Instrument cluster(A1)	No Fault
SCCM - Steering Column module(N80)	No Fault
PTS - PARKTRONIC(N62)	No Fault
ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)	No Fault
ZAN - Audio/COMAND display(A40/8)	No Fault
Audio 20/COMAND-Audio Or COMAND(A2-A40/3)	No Fault
DCU_FL - Left Front door(N69/1)	No Fault
DCU_FR - Right Front door(N69/2)	No Fault
AC - Air Conditioning(N22/7)	No Fault
LIN: N70 - Overhead control panel(OCP)	No Fault
LIN: N32/1 - Control module for seat adjustment and (or) seat heater "Driver" (ESA "Driver")	No Fault
LIN: B95 - Battery sensor(BSN)	No Fault
LIN: B38/2 - Rain/light sensor(RGLS)	No Fault
LIN: N72/1 - Upper control panel(UCP)	No Fault
LIN: H3/1 - Alarm siren (AS)	No Fault