

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-05-31 11:44:25
Technician Name: Hendrie
Order no:
Service fee:
Notes:

Vehicle Information

Make: SPRINTER
Model: Left-hand Steering
VIN: WDF44770323637132
Displacement: G 1.4 MPI KAPPA
Vehicle Software Version: V10.20

Inspection Result

The following systems are OK:

1. ECM - Engine Control Module
2. ISM - Shift Module
3. FSCU - Control Unit 'Fuel Pump'
4. SCR - Selective Catalytic Reduction
5. VGS - Fully Integrated Transmission Control
6. ES - Electrical Power Steering
7. ESP - Electical Stabillity Program
8. SAM - Signal Acquisition And Actuation Module
9. EZS - Electronic Ignition Lock
10. SRS - Supplemental Restraint System
11. SCM - Steering Column Module
12. AAG - Trailer Recognition
13. RD - Radio
14. IC - Instrument Cluster
15. DCU - LF - Left Front Door
16. DCU - RF - Right Front Door
17. AAC - Air Conditioning