

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:01/27/2025 14:00:08
Technician Name:Hennie

Vehicle Information

Make:BENZ
Model:253.309 - GLC 250 d 4MATIC Coupe
VIN:WDC2533092F437477
Odometer:89071 miles
Vehicle Software Version:V10.98

Inspection Result

SG-SW_L - Left Headlamp 1 problems exist

1.B178387 Control unit "LED driving lights actuation module" has CURRENT and STORED a malfunction.The message is missing.

SG-SW_R - Right Headlamp 1 problems exist

1.B178387 Control unit "LED driving lights actuation module" has CURRENT and STORED a malfunction.The message is missing.

DCU_FL - Left Front Door 1 problems exist

1.B18E62A Switch "Power window" has a malfunction.There is no CURRENT and STORED signal change.

The following systems are OK:

- 1.CDI - Engine Control Module(ECM)
- 2.PTCU - Drivetrain
- 3.FSCU - Fuel Pump
- 4.SCR-Selective
- 5.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 6.N68 - Electrical Power Steering (ES)
- 7.ESP - Electronic Stability Program
- 8.KAB - Camera Cover
- 9.PTS - PARKTRONIC
- 10.RFK - Backup Camera
- 11.SG_AWF - COLLISION PREVENTION ASSIST
- 12.RDK - Tire Pressure Monitor
- 13.ATA - Interior Motion Sensor
- 14.EIS/EZS - Electronic Ignition Lock
- 15.KG - KEYLESS GO
- 16.SCM - Steering Column Module
- 17.Driver-side SAM - Front Signal Acquisition And Actuation Module