

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 11/13/2024 14:27:49

Technician Name: Wimpie F

Vehicle Information

Make: BENZ

Model: 207.365 - E 400 Blue

VIN: WDD2073652F339514

Displacement: G 1.0 T-GDI KAPPA

Odometer: 87674 km

Vehicle Software Version: V10.98

Inspection Result

ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1) 1 problems exist

1.9eaf97 Easy entry/exit has a malfunction. The system function is CURRENT and STORED restricted.

AC - Air Conditioning(N22/7) 1 problems exist

1.911315 Temperature sensor "Right footwell vent" has a malfunction. There is a short circuit to positive or an open circuit. CURRENT and STORED

The following systems are OK:

1.FSCU - Control Unit'Fuel pump'(N118)

2.ISM - Intelligent Servo Module(A80)

3.ME - MOTOR ELECTRONICS FOR COMBUSTION ENGINE(ECM)

4.VGS/ETC - Transmission Control Module(TCM)

5.ES - Electrical Power Steering(N68)

6.ESP - Electronic Stability program(N30/4)

7.SG_AWF - COLLISION PREVENTION ASSIST

8.IRS-HRA - Outer Right Rear Intelligent Radar Sensor system(B29/5)

9.IRS-HLA - Outer Left Rear Intelligent Radar Sensor system(B29/4)

10.MFK - Multifunction camera(A40/11)

11.PTS - PARKTRONIC(N62)

12.360 Degree camera(N148)

13.TPC - Tire Pressure Monitoring System(TPMS)(N88)

14.EIS/EZS - Electronic Ignition lock(N73)

15.KG - KEYLESS GO(N69/5)

16.SCCM - Steering Column module(N80)

17.SD - Sliding Roof/Panoramic Sliding Sunroof

18.RevGUS_VL - Left Front Reversible Emergency Tensioning retractor(A76)