

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-10-07 16:34:57
Technician Name:john
Order no:
Service fee:
Notes:

Vehicle Information

Make:BENZ
Model:169.007 - A 180 CDI
VIN:WDD1690072J939707
Odometer:87624 km
Vehicle Software Version:V10.84

Inspection Result

The following systems are OK:

- 1.ESM - Electronic Selector Module
- 2.VGS/ETC - Transmission Control Module(TCM)
- 3.CDI - Engine Control Module(ECM)
- 4.ESP - Electronic Stability Program
- 5.ES - Electronic Power Steering
- 6.AB - Supplemental Inflatable Restraint System(SRS)
- 7.EIS - Electronic Ignition Switch(Without Keyless GO)
- 8.OCP - Overhead Control Panel
- 9.UCP - Upper Control Panel
- 10.SAM - Signal Acquisition And Actuation Module
- 11.ATA - Anti-theft Alarm System
- 12.IC - Instrument Cluster
- 13.SCM - Steering Column Module
- 14.PTS - PARKTRONIC
- 15.COMAND/AUDIO - Audio 50(Display And Operating Unit With Navigation) Or COMAND(Display And Operating Unit)
- 16.DCM_FL - Door Control Module Front Left
- 17.DCM_FR - Door Control Module Front Right
- 18.DCM_RL - Door Control Module Rear Left
- 19.DCM_RR - Door Control Module Rear Right