

Diagnostic Report

THINKCAR

Time: 01/06/2025 13:13:07

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Gezina	Telephone: N/A
Email: pieter	Country: South Africa
State: Gauteng	City: Pretoria
Address1: N/A	Address2: N/A

Make: HYUNDAI	Model: Venue(QXI)
Year: 2021	Displacement: G 1.0 T-GDI KAPPA
VIN: MALFC81ALMM146569	Odometer: 57212 km
License #: N/A	Vehicle Software Version: V10.40

Pre-Scan

01/06/2025 13:13:07

System(13)	Status
ECM (Engine Control Module)	No Fault
ABS (Anti-lock Braking System)	No Fault
Airbag(Event #1)	No Fault
Airbag(Event #2)	No Fault
AC (Air Conditioning)	No Fault
Integrated Body Control Unit-BCM	No Fault
Integrated Body Control Unit-SMK	No Fault
Integrated Body Control Unit-IMMO	No Fault
IC (Cluster Module)	No Fault
Integrated Body Control Unit-TPMS	No Fault

MDPS (Motor Driven Power Steering)	No Fault
ICCU (Integrated Central Control Unit)	No Fault
CODE (Transmitter Code Saving)	No Fault