

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15928

Make	HYUNDAI	
Model	TUCSON 2.0 PREMI	UM
Vin	KMHJ2813LGU15037	76
Engine Specifications	2.0	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2016
Km	143709
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	-	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	-	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	•
Side Mirrors / Electric	No Fault Code	-	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Oil Service	DUE FOR SERVICE Km	Dip Stick	Within Specification	•
Oil Filter	Good Condition	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	Fan Belt	Not Applicable	•
Air Filter	Good Condition	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	Within Specification	•
Spark Plugs	No Fault Code	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	Aircon Belt	Within Specification	•
Antifreeze	No Visible Leaks	Multi V belt	Within Specification	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Within Specification	-
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	-
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	-
Throttle	No Fault Code	-
Turbo	Not Applicable	-
Injectors	No Fault Code	-
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

Dries Olwagen

NEW Technician

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

