

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-09-03 11:54:32

Technician Name: Elias

Order no:

Service fee:

Notes:

## Vehicle Information

Year: 2019

Make: USAFORD

Model: Ranger / Mazda B-Ser

VIN: AFANXXMJ2NKJ53827

Displacement: D 2.0 TCI-R

Odometer: 114969 miles

Vehicle Software Version: V10.76

## Inspection Result

FCDIM (Front Control/Display Interface Module) 1 problems exist

**1.U0184:00-AF Missing Communication With RADIO**

**Continuous Memory DTCs**

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.APIM (Accessory Protocol Interface Module)
- 3.BCMII (Body Control Module)
- 4.FCIM (Front Controls Interface Module)
- 5.GWM (Gateway Module A)
- 6.IPC (Instrument Panel Control Module)
- 7.PAM (Parking Aid Module)
- 8.PCM (Powertrain Control Module)
- 9.PSCM (Power Steering Control Module)
- 10.RCM (Restraint Control Module)
- 11.RTM (Radio Transceiver Module)
- 12.SCCM (Steering Column Control Module)
- 13.TRM (Trailer Module)