All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars Address:564 Steve Biko Road Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2023-12-23 08:59:19 Technician Name:Wimpie F Customer Name:citton cars

Vehicle Information

Make:Mitsubishi

VIN: JMYXTGK1WMZ001426

Odometer:40438 km

Vehicle Software Version:V10.28

Inspection Result

LIN 4 problems exist

1.L0440 RLS High Temperature Detect	Stored
2.L0440 RLS High Temperature Detect	Active
3.L0442 RLS Low Temperature Detect	Stored
4.L0442 RLS Low Temperature Detect	Active

The following systems are OK:

1.MPI/GDI/DIESEL

2.AT/CVT/A-MT/TC-SST

3.4WS/Electric Power Steering

4.ABS/ASC/ASTC/WSS

5.SRS-Air Bag

6.Air Conditioner

7.ETACS

8.KOS/Immo/Keyless

9.EPB

10.Meter

11.Steering Angle Sensor

12.Audio

13.CORNER SENSOR/SONAR

14.HUD

15.Multi Channel Gateway