

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton Cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:mariska@boschgezina.co.za  
Sn:988579800333  
Time:2024-02-26 15:41:16  
Technician Name:Lu-André  
Customer Name:bosch

## Vehicle Information

Year:2015  
Make:TOYOTA  
Model:Fortuner/Hilux SW4  
VIN:AHTCB3GS902003924  
Displacement:G 1.4 DOHC  
Odometer:99606.00 km  
Vehicle Software Version:V10.44

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.AC (Air Conditioning)
- 7.FWD (Four Wheel Drive)
- 8.CM (Combination Meter)
- 9.SC (Starting Control)
- 10.NS (Navigation System)
- 11.ES (Entry&Start)
- 12.PSC (Power Source Control)