Make	MERCEDES-BENZ		
Model	VITO 111 1.6 CDI F/C P/V		
Vin	WDF44760323498612	2	
Engine Specifications	1.6	Diesel ▼	
Vehicle Type	1.6 P/V	Diesel	

Year	2018
Km	186446
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	<b>—</b>	Aircon Controls	Working Condition	<b>T</b>
Cluster	No Fault Code	<b>V</b>	Electric Windows	Working Condition	•

Exterior			
Windscreen	-Select-	Mag Wheels	-Select-
Side Mirrors / Electric	-Select-	Wiper Blades	-Select-

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km	n	Dip Stick	Within Specification	•
Oil Filter	Good Condition	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Not Applicable	<b>-</b>	Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable	•	Power Steering Belt	No Cracks	•
Brake Fluid	Good Condition	<b>-</b>	Aircon Belt	Not Applicable	•
Antifreeze	No Visible Leaks	•	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	<b>•</b>	PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	40%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	•
Aircon Condensor	Not Applicable	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	<b>~</b>

Fueling System		
Intake Manifold	No Visible Leaks	•
Throttle	No Fault Code	lacksquare
Turbo	No Fault Code	lacksquare
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	lacksquare

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	No Visible Leaks	<b>—</b>
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	
CV Joints	No Visible Leaks	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	
Shocks Rear	No Visible Leaks	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	lacksquare
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	<b>V</b>

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	No Visible Leaks	lacksquare
Clutch Slave	No Visible Leaks	lacksquare
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	lacksquare
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



**PRETORIA** 

