

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:mariska@boschgezina.co.za  
Sn:988579800333  
Time:2024-03-25 08:01:19  
Technician Name:shaun  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2022  
Make:USAFORD  
Model:EcoSport  
VIN:MAJAXXMRKANJ12904  
Displacement:G 1.2 MPI KAPPA  
Odometer:64409 km  
Vehicle Software Version:V10.62

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.GWM (Gateway Module A)
- 6.HVAC (Heating Ventilation Air Conditioning)
- 7.IPC (Instrument Panel Control Module)
- 8.PAM (Parking Aid Module)
- 9.PCM (Powertrain Control Module)
- 10.PSCM (Power Steering Control Module)
- 11.RCM (Restraint Control Module)
- 12.SCCM (Steering Column Control Module)