

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Repair Shop

Shop Name: Bosch service center
Address: 504 Swemmer Street Pretoria
Zip Code:
Telephone: 012 335 5737
Email: juan-dre@boschgezina.co.za
SN: 987596007339
Test Time: 2024-04-15 13:18:20
Technician Name: Basal



Vehicle Information

Year: 2019
Make: Hyundai
Model: Kona(OS)
VIN: KMHK381AMKU191262
Engine Size: D 1.6 NEW-U MHEV
Odometer: 50183 km
Vehicle Software Version: V51.60
Diagnostic Application Version: V7.05.024
Diagnostic path: 16 PIN DLC > Manually Select > General Area > Kona(OS) > 2019 > G 2.0 MPI



System fault code

The following systems are OK:

1. ECM (Engine Control Module)
2. TCM (Transmission Control Module)
3. ABS (Anti-lock Braking System)
4. Airbag(Event #1)
5. Airbag(Event #2)
6. IBU-TPMS
7. IBU-BCM
8. IC (Cluster Module)
9. MDPS (Motor Driven Power Steering)
10. BCW (Blind-Spot Collision Warning)
11. Blind-Spot Collision Warning(Ironman)
12. RVM (Rear View Monitor)

13.IMMO (Immobilizer)

14.Integrated Gateway Power Module

15.CODE (Transmitter Code Saving)