All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars Address:564 Steve Biko Road Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-03-30 09:58:05 Technician Name:Raymond

Order no: Service fee: Notes:

Vehicle Information

Make:TOYOTA
Model:Urban Cruiser
VIN:JTDPYGJ1S00990006
Displacement:G 1.0 MPI KAPPA
Odometer:022394 km
Vehicle Software Version:V10.44

Inspection Result

The following systems are OK: 1.EOBD/OBD II 2.ECMECT (Engine and ECT)