

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:lukas@boschgezina.co.za
Sn:988579800333
Time:2024-04-16 15:10:02
Technician Name:Lu-André
Order no:
Service fee:
Notes:

Vehicle Information

Year:2014
Make:USAFORD
Model:EcoSport
VIN:MAJAXXMRKAEJ68045
Displacement:G 2.0 MPI
Odometer:154610 km
Vehicle Software Version:V10.76

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.FCDIM (Front Control/Display Interface Module)
- 6.HVAC (Heating Ventilation Air Conditioning)
- 7.IPC (Instrument Panel Control Module)
- 8.PCM (Powertrain Control Module)
- 9.PSCM (Power Steering Control Module)
- 10.RCM (Restraint Control Module)
- 11.TCM (Transmission Control Module)