

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-05-31 11:17:23
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Year:2018
Make:MAZDA
Model:CX-5
VIN:JM6KF2W7AJ0149285
Displacement:G 1.4 MPI KAPPA
Odometer:113302 km
Vehicle Software Version:V10.34

Inspection Result

The following systems are OK:

- 1.F_BCM (Front Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.R_BCM (Rear Body Control Module)
- 5.RCM (Restraint Control Module)
- 6.TCM (Transmission Control Module)
- 7.ABS (Anti-Lock Brake System)
- 8.AFS/ALM (Adaptive Front Lighting System/Auto Leveling Module)
- 9.EATC#1 (Electronic Air Temperature Controller)
- 10.CMU (Connectivity Master Unit)
- 11.EPB (Electrical Parking Brake)
- 12.EPS (Electronic Power Steering)
- 13.SSU#1 (Start Stop Unit)