

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:11/11/2024 15:15:34
Technician Name:shaun

Vehicle Information

Year:2002
Make:BENZ
Model:117.303 - CLA 220 CD
VIN:WDD1173032N459515
Displacement:G 1.4 DOHC
Odometer:114286 km
Vehicle Software Version:V10.88

Inspection Result

The following systems are OK:

- 1.CPC - Common Power Train Controller
- 2.FSCU - Fuel Pump
- 3.CDI - Engine Control Module(ECM)
- 4.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 5.EFB - Electrical Parking Brake(EPB)
- 6.ES - Electronic Power Steering
- 7.ESP - Electronic Stability Program
- 8.TPC - Tire Pressure Monitoring System(TPMS)
- 9.SG_AWF - COLLISION PREVENTION ASSIST
- 10.EIS/EZS - Electronic Ignition Lock
- 11.ATA - Interior Motion Sensor
- 12.MFK - Multifunction Camera
- 13.SCM - Steering Column Module
- 14.SD - Sliding Roof/Panoramic Sliding Sunroof
- 15.RFK - Backup Camera
- 16.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 17.AB - Supplemental Restraint System(SRS)
- 18.SG-SW_L - Left Headlamp
- 19.SG-SW_R - Right Headlamp
- 20.CPF - Camera Cover
- 21.Audio - Audio Or COMAND
- 22.IC - Instrument Cluster
- 23.PTS - PARKTRONIC
- 24.ZAN - Audio/COMAND Display

- 25.COU[ZBE] - Audio/COMAND Operating Unit
- 26.SG-MSND - Engine Sound
- 27.DCU_FL - Left Front Door
- 28.DCU_FR - Right Front Door
- 29.AC - Air Conditioning
- 30.LIN: H3/1 - Alarm siren (AS)
- 31.LIN: N70 - Overhead control panel(OCP)
- 32.LIN: B95 - Battery sensor(BSN)
- 33.LIN: B38/2 - Rain/light sensor(RGLS)
- 34.LIN: N72/1 - Upper control panel(UCP)