

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-11 08:53:48

Technician Name:john

Order no:

Service fee:

Notes:

Vehicle Information

Make:CHANGCHENG

Model:HAVAL JOLION FUEL

VIN:LGWEE4A51NK618777

Displacement:D 2.0 TCI-R

Odometer:38620 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM(Engine Control Module(UAES-4G15H&4G15K))
- 2.TCU(Transmission Control Unit 7DCT-300S)(UAES)
- 3.ESP(Electronic Stability Program)
- 4.ABM (Airbag Module)
- 5.KBCM(KOSTAL Elec Region Control System Body)
- 6.IP(Instrument Panel 3.5 Inch Vikeer)
- 7.GW(Independent Gateway)
- 8.AC(Air Conditioning)
- 9.RPAS(Rear Park Assistantsystem)
- 10.CSA(Combination Switch Assembly)
- 11.EPS(Electric Power Steering BOSCH)
- 12.F-PBOX(Front Power Box)
- 13.R-PBOX(Rear Power Box)
- 14.HUT(Head Unit(Harman))
- 15.SBWM(Shift By Wire Module(MANDE))
- 16.TPMS(Tyre Pressure Monitoring System)